



This report provided free of charge by:

Driven Automotive
1213 W Wetmore Rd
Tucson, AZ 85705
520-655-6593



Report

US \$44.99

2014 Volkswagen Jetta SE Pzev

118,498 mi | VIN: 3VWD17AJXEM227535 |

Sedan 4 DR | 1.8L I4 F DOHC 16V | Gasoline | Front wheel drive

CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**DAMAGE** Minor Damage

Minor

Moderate

Severe

CARFAX VALUE \$7,230

23 Service History Records



At Least 1 Open Recall



3 Previous Owners



Types of Owners: Rental, Personal



Last Owned in Arizona

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/6/26 at 7:32:00 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Accident / Damage History

Not all accidents / issues are reported to CARFAX

Event 1

11/14/2014

Damage reported: minor damage


Damage Severity Scale



Minor

Moderate

Severe



Event 2

10/08/2018

Damage reported: minor damage


Damage Severity Scale



Minor

Moderate

Severe





Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	✓ Oil and filter changed	01/29/2026
Flushes	✓ Antifreeze/coolant flushed/changed	01/29/2026
This car has been recently serviced. That's a good thing!		



History-Based Value Report

\$7,230
CARFAX Retail Value

History events affecting this vehicle's value

- Service History
- Open Recall
- Non-Personal Vehicle
- Minor Damage



Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

Owner 2

Owner 3

Total Loss

No total loss reported to CARFAX.

✓ No Issues Reported

✓ No Issues Reported

✓ No Issues Reported

Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

✓ No Issues Reported

✓ No Issues Reported

✓ No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.

✓ No Issues Reported

✓ No Issues Reported

✓ No Issues Reported

Odometer Check

No indication of an odometer rollback.

✓ No Issues Indicated

✓ No Issues Indicated

✓ No Issues Indicated

Accident / Damage

Damage reported: 11/14/2014 and 10/08/2018.

Minor Damage

Minor Damage

No New Issues Reported

Manufacturer Recall

At least 1 manufacturer recall requires service. Locate an authorized Volkswagen dealer to obtain more information about this recall.

✓ No Recalls Reported

Recall Reported

No New Recalls Reported

Basic Warranty

Original warranty estimated to have expired.

Warranty Expired

Warranty Expired

Warranty Expired



Title History

CARFAX guarantees the information in this section

Owner 1

Owner 2

Owner 3

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

✓ Guaranteed No Problem

✓ Guaranteed No Problem

✓ Guaranteed No Problem

Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

✓ Guaranteed No Problem

✓ Guaranteed No Problem

✓ Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

CARFAX Ownership History The number of owners is estimated	Owner 1	Owner 2	Owner 3
Year purchased	2013	2017	2026
Type of owner	Rental	Personal	Personal
Estimated length of ownership	3 yrs. 3 mo.	8 yrs. 8 mo.	12 days
Owned in the following states/provinces	Hawaii, Arizona	Arizona	Arizona
Estimated miles driven per year	11,178/yr	8,676/yr	---
Last reported odometer reading	41,853	118,498	---

CARFAX


Detailed History

Owner 1
Purchased: 2013


Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Rental Vehicle
11,178 mi/yr

Date	Mileage	Source	Comments
11/30/2013		NICB	Vehicle manufactured and shipped to original dealer
12/05/2013	5	Hawaii Motor Vehicle Dept. Kahului, HI Title #LED50613	Vehicle purchase reported - Title issued or updated - Registration issued or renewed - First owner reported - Loan or lien reported - Titled or registered as rental vehicle - Vehicle color noted as Silver
11/07/2014		Hawaii Motor Vehicle Dept. Kahului, HI Title #LED50613	Title or registration issued - Loan or lien reported - Vehicle color noted as Silver
11/14/2014		Damage Report	Damage reported: minor damage - Damage to front



CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

07/08/2015	18,480	Honolulu Volkswagen Honolulu, HI 808-834-6288 honoluluvw.com/ ★ 4.3 / 5.0 148 Verified Reviews ♥ 103 Customer Favorites		Vehicle serviced - Battery/charging system checked - Battery replaced - Battery serviced - Computer reprogrammed
10/26/2015		Hawaii Motor Vehicle Dept. Kahului, HI Title #LED50613		Title issued or updated - Title or registration issued - Loan or lien reported
01/07/2016		Hawaii Motor Vehicle Dept. Kahului, HI Title #LED50613		Registration issued or renewed - Loan or lien reported - Vehicle color noted as Silver
03/25/2016	26,608	Honolulu Volkswagen Honolulu, HI 808-834-6288 honoluluvw.com/ ★ 4.3 / 5.0 148 Verified Reviews ♥ 103 Customer Favorites		Vehicle serviced - Console repaired
11/09/2016		Hawaii Motor Vehicle Dept. Kahului, HI Title #LED50613		Title or registration issued - Loan or lien reported - Vehicle color noted as Silver
03/27/2017	37,000	Auto Auction		Vehicle sold Millions of used vehicles are bought and sold at auction every year.
04/04/2017		Dealer Inventory		Vehicle offered for sale
04/05/2017		MPG Automotive Services- Casa Grande Casa Grande, AZ 520-836-6010 ★ 5.0 / 5.0 9 Verified Reviews		Vehicle serviced - Maintenance inspection completed - A/C refrigerant recharged - Air filter replaced - Battery/charging system checked - Brake pads replaced - Brake rotor(s) resurfaced - Cabin air filter replaced/cleaned - Fluids checked - Front brake pads replaced - Front wiper blades/refills replaced - Oil and filter changed - Rear brakes replaced - Tire condition and pressure checked - Tire(s) balanced

- Tire(s) replaced
- Tires rotated
- Wiper(s) replaced

04/19/2017 37,019 MPG Automotive Service
Tucson, AZ
520-744-7997
★ **4.8 / 5.0** 84 Verified Reviews
♥ **45** Customer Favorites

**Vehicle serviced**

05/12/2017 Arizona
Motor Vehicle Dept.
Tucson, AZ
Title #0E04017151084

Title issued or updated

- Registration issued or renewed
- Dealer took title of this vehicle while it was in inventory
- Title or registration issued

06/09/2017 39,070 Big Brand Tire
TUCSON, AZ
520-882-7253
★ **4.7 / 5.0** 47 Verified Reviews
♥ **28** Customer Favorites

**Vehicle serviced**

- Maintenance inspection completed
- A/C system checked
- Battery/charging system checked
- Tire condition and pressure checked

07/21/2017 41,853 Big Brand Tire
TUCSON, AZ
520-882-7253
★ **4.7 / 5.0** 47 Verified Reviews
♥ **28** Customer Favorites

**Vehicle serviced**

- Battery/charging system checked
- Battery replaced

Owner 2
Purchased: 2017

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
8,676 mi/yr

Date	Mileage	Source	Comments
07/24/2017		Arizona Motor Vehicle Dept. Tucson, AZ Title #AZ04017205062	Title issued or updated - Registration issued or renewed - Title or registration issued - New owner reported - Loan or lien reported
08/05/2017	43,017	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Oil and filter changed
10/12/2017	48,218	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Body lubricated - Fluids checked - Oil and filter changed - Tires rotated
04/03/2018	52,697	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Front wiper blades/refills replaced - Oil and filter changed - Tires rotated - Wiper(s) replaced
10/08/2018		Damage Report	Damage reported: minor damage - Damage to right front - Damage to front

Damage Severity Scale


CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION



Minor

Moderate

Severe



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

11/05/2018 57,764 Big Brand Tire
TUCSON, AZ
520-882-7253
★ 4.7 / 5.0 47 Verified Reviews
♥ 28 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Battery/charging system checked
- Fluids checked
- Oil and filter changed
- Tires rotated

06/10/2019 63,000 Arizona
Inspection Station
Pima County

Passed emissions inspection

06/15/2019 63,384 Big Brand Tire
TUCSON, AZ
520-882-7253
★ 4.7 / 5.0 47 Verified Reviews
♥ 28 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Battery/charging system checked
- Fluids checked
- Front wiper blades/refills replaced
- Oil and filter changed
- Tires rotated

08/27/2019 Volkswagen

Manufacturer Compliance Recall issued

- NHTSA #19V615
- Recall #37M2 MICRO SWITCH
- Status: Remedy Available

Locate an authorized Volkswagen dealer to obtain more information about this recall

● [Learn more about this recall](#)

Description: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy: Install an additional switch and circuit board.

11/16/2019 67,573 Big Brand Tire
TUCSON, AZ
520-882-7253
★ 4.7 / 5.0 47 Verified Reviews
♥ 28 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Battery/charging system checked
- Body lubricated
- Fluids checked
- Oil and filter changed

06/15/2020 Arizona
Motor Vehicle Dept.
Tucson, AZ
Title #AZ04017205062

Registration issued or renewed

- Loan or lien reported
- Registration updated when owner moved the vehicle to a new location

07/06/2020	72,028	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Front wiper blades/refills replaced - Oil and filter changed - Tires rotated - Wiper(s) replaced
12/07/2020	75,101	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Oil and filter changed - Tires rotated
06/15/2021	78,689	Arizona Inspection Station Pima County		Passed emissions inspection
06/15/2021		Arizona Motor Vehicle Dept. Tucson, AZ Title #A004456450		Title issued or updated - Title or registration issued - Loan or lien released
08/20/2021	80,388	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Front wiper blades/refills replaced - Oil and filter changed - Tires rotated - Wiper(s) replaced
01/06/2022	84,186	Big Brand Tire TUCSON, AZ 520-882-7253 ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Battery/charging system checked - Fluids checked - Oil and filter changed - Tires rotated
11/29/2022	92,016	Big Brand Tire Tucson, AZ 520-882-7253 bigbrandtire.com ★ 4.7 / 5.0 47 Verified Reviews ♥ 28 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
06/19/2023	97,377	Arizona Inspection Station Pima County		Passed emissions inspection
06/21/2023	97,440	Bill Nelson's Automotive Tucson, AZ 520-747-5900 ★ 4.8 / 5.0 39 Verified Reviews ♥ 19 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
06/21/2023		Arizona Motor Vehicle Dept. Tucson, AZ Title #A004456450		Registration issued or renewed
10/27/2023	100,684	Independent Volkswagen And Audi Services Tucson, AZ 520-747-0044 independentvwaudi.com/ ★ 5.0 / 5.0 184 Verified Reviews ♥ 151 Customer Favorites		Vehicle serviced - Ignition coil(s) replaced - Spark plug(s) replaced

03/08/2024	101,995	Bill Nelson's Automotive Tucson, AZ 520-747-5900 ★ 4.8 / 5.0 39 Verified Reviews ♥ 19 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Brakes checked - Brake caliper(s) replaced - Brake fluid flushed/changed - Brake master cylinder replaced/repared - Brake pads replaced - Brake rotor(s) replaced - Fluids checked - Oil and filter changed - Rear brake caliper(s) replaced - Rear brake pads replaced - Rear brake rotor(s) replaced - Tire condition and pressure checked - Wiper(s) replaced
09/11/2024	107,088	Jiffy Lube Tucson, AZ 520-887-5077 jiffylube.com/ ★ 4.6 / 5.0 52 Verified Reviews ♥ 1,131 Customer Favorites		Vehicle serviced - Air filter checked - Antifreeze/coolant checked - Brake fluid checked - Drive belts checked - Exterior lights checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
02/13/2025		Arizona Motor Vehicle Dept. Tucson, AZ Title #A004456450		Registration issued or renewed
06/12/2025	113,796	Arizona Inspection Station Pima County		Passed emissions inspection
08/21/2025	114,610	Jiffy Lube Tucson, AZ 520-886-0587 jiffylube.com/ ★ 4.8 / 5.0 92 Verified Reviews ♥ 2,769 Customer Favorites		Vehicle serviced - Air filter replaced - Antifreeze/coolant checked - Brake fluid checked - Drive belts checked - Exterior lights checked - Oil and filter changed - Tire condition and pressure checked - Transfer case fluid checked - Wipers/washers checked - Vehicle washed/detailed
01/29/2026	117,223	Independent Volkswagen And Audi Services Tucson, AZ 520-747-0044 independentvwaudi.com/ ★ 5.0 / 5.0 184 Verified Reviews ♥ 151 Customer Favorites		Vehicle serviced - Antifreeze/coolant flushed/changed - Camshaft seal(s) replaced - Drivability/performance checked - Engine timing/front cover gasket replaced - Intake manifold replaced - Oil and filter changed - Oil cooler seal(s) replaced - Water pump replaced
04/11/2026	118,396	Desert Toyota of Tucson Tucson, AZ 520-296-8535 deserttoyota.com/ ★ 4.6 / 5.0 517 Verified Reviews ♥ 32 Customer Favorites		Vehicle offered for sale
04/21/2026	118,498	Arizona Inspection Station Pima County		Passed emissions inspection
 Owner 3 Purchased: 2026 Personal Vehicle				
Date	Mileage	Source	Comments	

04/24/2026

Arizona
Motor Vehicle Dept.
Tucson, AZ
Title #A004456450

Registration issued or renewed
- New owner reported

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/6/26 at 7:32:00 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Rental

Vehicle was registered by a rental agency.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX [@CARFAXinc](https://twitter.com/CARFAXinc) [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
5/6/26 7:32:00 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 VOLKSWAGEN JETTA vehicle (VIN: 3VWD17AJXEM227535), which is based on information supplied to CARFAX and available as of 5/6/26 at 8:32 PM (EDT).

Customer Signature

Date

Dealer Signature

Date